

# Michigan Fire Alarm Inspections

PO Box 90283 Burton, MI 48509  
Phone 810-955-9599

## FIRE ALARM INSPECTION REPORT

Annual inspection  Semi-annual inspection  Quarterly

Inspection site Richfield Public  
Address 3807 N Center Rd  
City, State Zip FLINT MI 48506

Customer SAMC  
Address \_\_\_\_\_  
City, State Zip \_\_\_\_\_

Site Contact Tony

Phone 810 736 1281

Disconnected power supply  Notified offsite personnel Last date of service/inspection 2012

Condition of system upon arrival:  Normal  Trouble

System Panel Manufacturer: FARADAY 1200 Battery 12VDC 82 year 2012  
 Sealed lead  Dry cell

### Notification

- Bells
- Mini-horns
- Horn/strobes
- Speakers
- Strobe lights

### Initiating Devices

- Manual stations
- Smoke detectors
- Heat detectors
- Flow switches
- Tamper switches
- Duct smoke detector

### Trouble Signal

- Control Panel
- Charger Function
- Power Supply
- Supervisory Signal
- Alarm Signal
- Restore Signals

### Monitor Type

- Type of Transmission
- Digital
- Call Box
- Interface equipment
- None

- Fire alarm panel is operational
- Smoke detectors are operational
- Remote annunciation
- Door holder

- Light and LED's are operational
- Horns/ Strobes are operational
- LED light & functional signals verified
- Supervisory devices

- Battery voltage is satisfactory
- Power supply is operational
- Relays in base and working
- Flow delay time: 30 45 60 90

- All initiating devices tested O.K.
- Except (see problems discovered)

- All remote devices tested O.K.
- Except (see problems discovered)

- All other devices tested O.K.
- Except (see problems discovered)

- All signaling devices tested O.K.
- Except (see problems discovered)

- All control devices tested O.K.
- Except (see problems discovered)

### Post inspection:

- Clear panel of all alarms
- Enable all alarm devices
- Clear panel of all trouble
- Restore AC power

Ending battery voltages: A 12.3 volts B 12.4 volts Power supply: Main 110VAC Secondary 24VDC

Problems discovered HORN / STROBE NOT WORKING SMOKE NOT WORKING

Repairs completed: \_\_\_\_\_

# Michigan Fire Alarm Inspections

PO Box 90283 Burton, Mi 48509

Phone 810-955-9599

## FIRE ALARM INSPECTION REPORT

Condition of system on departure     Normal     Trouble

Recommendations \_\_\_\_\_

The following item(s) did not operate correctly \_\_\_\_\_

Inspection notes: Need to Replace Items with Trouble  
Horns / STrobe + Smoke Detector

License # 5201276

Technician

*J. Larne*

Date

9/14/13